

PHOTOGRAPH LOG

DESCRIPTION OF PHOTOGRAPH	PHOTOGRAPH NUMBER
Former Aggregate Yard Front Gate unlocked and open. Entrance is obstructed by large waste container. Waste container holds small amount of metal waste. East Facing	20220810-JB-P01
Front gate placards “no trespassing” “authorized personnel only” Two empty drums East facing	20220810-JB-P02
Pebble pathway showing berm (left) South facing	20220810-JB-P03
Sedimentation Pond South facing	20220810-JB-P04
Sedimentation Pond berm, no fencing present at southern perimeter. Housing development shown in background. South facing	20220810-JB-P05
MW-7 East facing	20220810-JB-P06
Pine Creek Photo 1/3 South facing	20220810-JB-P07
Pine Creek Photo 2/3 South facing	20220810-JB-P08
Pine Creek Photo 3/3 Photo South facing	20220810-JB-P09
Pebble gravel path detail Photo 1/2	20220810-JB-P10
Pebble gravel path detail Photo 2/2	20220810-JB-P11
End of berm, not shown below photo is a concrete barrier blocking the path to Denali Landscaping. East facing	20220810-JB-P12
Sedimentation pond, note the soil is dry in appearance South facing	20220810-JB-P13

PHOTOGRAPH LOG

Berm and flat area adjacent to the sedimentation pond West facing	20220810-JB-P14
Pond 1/2 West facing	20220810-JB-P15
Pond 2/2 West facing	20220810-JB-P16
Gravel path, approximate location of the scale house South facing	20220810-JB-P17
MW-2 South facing	20220810-JB-P18
Material of the top of berm	20220810-JB-P19
Depression on top of berm	20220810-JB-P20
Top of berm looking towards Denali Landscaping Yard	20220810-JB-P21
Top of berm looking down at Denali Landscaping Yard	20220810-JB-P22
Top of berm North facing	20220810-JB-P23
Top of berm, sinkhole	20220810-JB-P24
Metal “ML” label and Danger placard on front gate.	20220810-JB-P25